

Gammeldags



The Turkish spindle has three parts, a spindle shaft and two wings

Assemble the wings, with the thin part into the bigger one. Make sure the holes fits.



The shaft is inserted from the bottom into the wings. The holes shall fit together.

Don't push down the wings. After a while they will go down to the bottom.

